## **Views From the Public Way**













### Informational Screening for Regional Impact Review of Proposed Demolition

Factor - Significance	Score	Comments/Data in Support				
Age (0-3 points)	1	The structure was constructed in 1897/1898.				
Historical/Cultural (0-3 points)	1	The Jolliffe House at 97 Iroquois Avenue (MHC (MHC 148) was constructed at the turn of the century, possibly for a member of the Jolliffe family who are identified on the 1911 map at this location. The map identifies both T.H. (Thomas H.) and A.B. (Aquis B.) Jolliffe at this address. The 1907 directory lists Mrs. T.H. Jolliffe of Brookline, MA as residing in West Chop. The Joliffe family acquired the property in 1898 from Trustees of the West Chop Land Company. The building was later owned by L. McCormick-Goodhart of Virginia for eighteen years. McCormick-Goodhart acquired the property in 1937. The next known owner of the property was Mrs. Irving Warner, who purchased it from McCormick-Goodhart.				
Design/Construction (0-3 points)	2	The structures holds the architectural detail and construction of the late 19 <sup>th</sup> century for the area of West Chop.				
Location/Visibility (0-2 points)	2	The north side of the structure is visible from Main Street as part of the neighborhood and the south side is visible from Iroquois Ave.				
Town Review (0-1 points)	1	The structure does not stand within a historic district.				
<b>TOTAL</b> (maximum = 13)	7	The matrix score of 7 categorizes the structure with limited significance, such that the Commission may determine concur or not concur.				

	Informational So	creening for DF	Review of Pro	oposed Demol	
					-
Historic/C	Cultural Significance				
Age:	Built before 1800	Built between 1800 and 1850	Built between 1850 and 1875	Built between 1875 and 1900	Built after 1900
	4	3	2		0
History/Co developm	ulture: Associated with in	ndividuals, orga	anizations, ever	nts, activities, p	batterns, or
developin	4	3	2	(1)	0
Design/Co	onstruction: Distinctive p	hysical and spa	atial characteris	tics, style, desi	igner, construction
	4	3	2	1	0
Contribut	ion to Context: Contribu	ting or integral	part of historic	streetscape, g	grouping, or area
	4	(3)	2	1	0
	Retains essential charac ce or which are reversibl		atures or has lat	er alterations	with acquired
	4	3	2	1	0
Historical	Designation: Federal, S	tate, Local			<b>A</b>
		3	2	1	(0)
					Total Historic Significance
Other Fac		1.15		act/choro/wh	are a higher score
Location/	Visibility: Visible from a relatively greater visibilit	v) (where a hig	ther number inc	dicates greater	visibility)
indicator			6	1	
indicates i	relatively greater violotin	3	12)	1 -	0
Condition	: Estimated order of mag better physical condition	3 gnitude of strue	cture condition re)	(where a high	er score indicates
Condition relatively	: Estimated order of mag better physical conditior	3 gnitude of struct n of the structu 3	re)	1	0
Condition relatively Safety Con	: Estimated order of may better physical conditior nsiderations: Has the bu	3 gnitude of struct n of the structu 3 ilding been det	re) 2 termined to be	1	0
Condition relatively Safety Con	: Estimated order of mag better physical conditior	3 gnitude of struct n of the structu 3 ilding been det	re) 2 termined to be	1	0
Condition relatively Safety Con higher nur	: Estimated order of map better physical condition nsiderations: Has the bu mber indicates greater s	3 gnitude of struct of the structu 3 ilding been det afety and secur 3	re) 2 termined to be rity) 2	1 not safe and n	0 ot secure? (where a
Condition relatively Safety Con higher nur Replacem	: Estimated order of map better physical condition nsiderations: Has the bu mber indicates greater si ent Program: A perman- idicates that a replacement	3 gnitude of struct of the structu 3 ilding been det afety and secur 3 ent replacemen	re) 2 cermined to be rity) 2 nt program has	1 not safe and n 1 been propose	0 ot secure? (where a 0 d (where a lower
Condition relatively Safety Con higher nur Replacem number in proceedin	: Estimated order of map better physical condition nsiderations: Has the bu mber indicates greater si ent Program: A perman- ndicates that a replacement g)	3 gnitude of structu of the structu 3 ilding been det afety and secur 3 ent replacemer ent program ha	re) cermined to be rity) 2 nt program has as been propose 2	1 not safe and n 1 been propose ed and is reaso	0 ot secure? (where a 0 d (where a lower onably assured of 0
Condition relatively Safety Con higher num Replacem number in proceedin Other Rev	: Estimated order of mag better physical condition nsiderations: Has the bu mber indicates greater si ent Program: A perman- idicates that a replacement	3 gnitude of structu of the structu 3 ilding been det afety and secur 3 ent replacement ent program ha 3 olition is subject	re) cermined to be rity) 2 nt program has as been propose 2 ct to a special p	1 not safe and n 1 been propose ed and is reaso 1 mermit or other	0 ot secure? (where a 0 d (where a lower onably assured of 0 r town review process
Condition relatively Safety Con higher num Replacem number in proceedin Other Rev	: Estimated order of map better physical condition nsiderations: Has the bu mber indicates greater si ent Program: A perman- idicates that a replacement g) view: The proposed dem	3 gnitude of structu of the structu 3 ilding been det afety and secur 3 ent replacement ent program ha 3 olition is subject	re) cermined to be rity) 2 nt program has as been propose 2 ct to a special p	1 not safe and n 1 been propose ed and is reaso 1 mermit or other	0 ot secure? (where a 0 d (where a lower onably assured of 0 r town review process
Condition relatively Safety Con higher num Replacem number in proceedin Other Rev	: Estimated order of map better physical condition nsiderations: Has the bu mber indicates greater si ent Program: A perman- idicates that a replacement g) view: The proposed dem	3    gnitude of structue    of the structue    3    ilding been deta    afety and secur    3    ent replacemer    ent program hat    3    olition is subject    en a higher num	re) ermined to be rity) 2 nt program has as been propose 2 ct to a special p nber indicates r	1 not safe and n 1 been propose ed and is reaso 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	0 ot secure? (where a 0 d (where a lower onably assured of 0 r town review process w).

**Historic/Cultural Significance:** The structure located at 97 Iroquois Ave, Tisbury (West Chop) was built in 1897/1898.

**History/Culture:** The structure is not associated with any person or event of historic significance.

**Design/Construction:** The structures holds the architectural detail and construction of the late 19th century for the area of West Chop.

**Contribution to Context:** The north side of the structure is visible from Main Street as part of the neighborhood and the south side is visible from Iroquois Ave.

**Integrity:** The house retains essential character-defining features of construction of the late 19<sup>th</sup> century but has been altered in the way of an added porch on the north side of the structure.

### Historical Designation: None

**Location/Visibility:** The north side of the structure is visible from Main Street as part of the neighborhood and the south side is visible from Iroquois Ave.

**Condition:** The home is in good condition except for the foundation and porch.

Safety Considerations: The structure is sound and safe.

**Replacement Program:** Proposed plans have been submitted for a new foundation and additions to be made to the north side of the house.

Other Review: None.


### Excerpt from MACRIS – Massachusetts Cultural Resource Information System

#### Excerpt from West Chop Area Inventory - 97 Iroquois Avenue


(Page 6): Continuing north along Main Street, north of its intersection with Iroquois Avenue, stands the Jolliffe House at 97 Iroquois Avenue (MHC 148). a 2'Z-story, gable-roof building sheathed in wood shingles with lattice underpinning along the foundation line. The building sits back from the road at the end of a dirt drive (identified as "Brud Warner Circle") leading off of Iroquois Avenue. The building's primary entrance is located on its southeast elevation within a 1-story, hip-roof, screened-in porch. A secondary entrance is located within a 1-story, integral porch with square posts on the southwest elevation. A ramp with iron rail leads up from the driveway to this porch. Oversized gable-roof dormers are located on both roof slopes. Fenestration consists of 12/12 and 9/2 double-hung sash windows within molded surrounds. The building features three interior, brick chimneys: one on the building's north roof slope, an other near the ridge, and the third at the south end of the building. A 1/2-story, side-gable, concrete block outbuilding features 6/6 double-hung sash windows. To the southeast of the south of the house. The outbuilding features 6/6 double-hung sash windows. To the southeast of the outbuilding stands a 1 V^-story, gable-roof garage (MHC 150) sheathed in wood shingles and set on a concrete foundation. The second outbuilding features a small, 1-story, shed-roof ell on its southeast elevation and 4/4 and 1/1 double-hung sash.

(Page 17): The Jolliffe House at 97 Iroquois Avenue (MHC (MHC 148) was constructed at the turn of the century, possibly for a member of the Jolliffe family who are identified on the 1911 map at this location. The map identifies both T.H. (Thomas H.) and A.B. (Aquis B.) Jolliffe at this address. At that time the building was much smaller and included only one outbuilding. The 1907 directory lists Mrs. T.H. Jolliffe of Brookline, MA as residing in West Chop. The Joliffe family acquired the property in 1898 from Trustees of the West Chop Land Company. According to a newspaper article located at the Dukes County Historical Society, the building was later owned by L. McCormick-Goodhart of Virginia for eighteen years. Under the ownership of Mr. McCormick-Goodhart, the house was known as "Wanakiwin," a name meaning quiet and peace. McCormick-Goodhart acquired the property in 1937. The next known owner of the property was Mrs. Irving Warner, who purchased it from McCormick-Goodhart. The Warner family continues to own the property to the present day.

# **The Proposed Plans**









### **Existing vs. Proposed Elevations**









#### October 27, 2020

#### Materials narrative for 97 Iroquois

- 1. Side wall shingles will be white cedar.
- 2. Roof shingles will be an architectural grade asphalt shingle to match existing.
- 3. Windows will be Marvin ultimate clad windows with 7/8" SDL muntins. Windows will match existing light cuts, 9/2, 12/2, etc.
- 4. Window and door exterior trim will match existing with  $5/4 \times 4$  trim with a back band.
- New exterior rake and eave trim will also match existing trim profiles.
  New lattice at foundation will match existing lattice.
- 7. New copper flashing will be 16oz bright copper.
- 8. New brick chimney will match existing brick chimneys.