

Massachusetts State Police Case Master Report 2022-117-170

Date Initiated 03/03/2022

Primary Information	n
Agency:	Massachusetts State Police
Bureau:	Division of Investigative Services
Division:	Investigative Services 1
Unit / Troop:	Fire & Explosion Investigation
Squad / Barracks:	Fire Investigation Southeast Team
Lead LEO:	Myers, Daniel T (MSP4190 / Fire Investigation Southeast Team / Massachusetts State Police)
Type Of Case:	Fire Investigation
Case Sub Type:	Undetermined
Case Description:	Fire Investigation- 16 Chapman Ave, Oak Bluffs
Case Priority:	Medium

Tips					
Number	Entry Date	Occurred Date	<u>Status</u>	Description	
2022-42469	03/04/2022 00:03		Closed		

Case Status	
Case Status:	Closed
Case Status Date:	06/02/2022
Disposition Code:	Closed/Completed
Disposition Date:	06/02/2022
Dissemination:	Chain of Command



Massachusetts State Police FIRE INVESTIGATION REPORT 2022-117-170

Report Date: 03/03/2022

Primary Information	
Description:	Fire Investigation- 16 Chapman Ave, Oak Bluffs
Dissemination Code:	report respect the security of its associated case
Reporting LEO:	Myers, Daniel T (MSP4190 / Fire Investigation Southeast Team / Massachusetts State Police)
Backup LEO:	Berteletti, Thomas (msp2708 / Fire Investigation Southeast Team / Massachusetts State Police)
Report Status:	Approved
Report Status Date:	05/05/2022
Approved By:	Berteletti, Thomas (msp2708 / Massachusetts State Police)
Discovered/Reported:	Fire Alarm
Requester:	Oak Bluffs Fire Department
Cause Of Fire:	Undetermined
COF Subcategory:	Undetermined
Injuries/Fatalities:	None
K9:	YES

Response Information	n
Time Call Received:	03/03/2022 09:49
Time Dispatched:	03/03/2022 12:45
Time Arrived:	03/03/2022 15:30
Time Completed:	03/03/2022 21:30

Property Information		
Property Description:	1.5 story wood frame, restaurant	
Property Use:	Commercial	
Mobile:	NO	
Single/Multi Story:	Other	
Square Footage:	15246	
Smoke Detectors:	YES	
Heat Detectors:	UNKNOWN	
Sprinklers:	NO	
CO:	UNKNOWN	
Occupied:	NO	
Abandoned:	NO	
Estimated Value:	\$2,000,000.00	
Estimated Loss:	\$2,000,000.00	
Type Of Insurance:	Commercial	
State Property:	Νο	

Fire Origin Information	
Area/Origin	Description



Massachusetts State Police FIRE INVESTIGATION REPORT 2022-117-170

Report Date: 03/03/2022

Fire Origin Info	ormation - Continued		
Area/Origin		Description	
Interior		A side, Main entrance ceiling	
			,
Insurance Info	rmation		
Insured:	SANTORO, MICHAEL J		

Insurance Company:Lloyd's of LondonInsurance Agent:Bernard, Zack

Synopsis

On Thursday, March 3, 2022, the Oak Bluffs Fire Department requested assistance with a fire Investigation at 16 Chapman Ave. Sgt Berteletti, Tpr Myers, Tpr Colella, and Tpr Garfield (CSSS) responded to the incident. At the scene, we met with Sgt Mackin, Tpr shaw, and Deputy Chief Foster and a joint investigation was conducted. Scene examination and interviews were completed. This incident involved a 1.5 half story commercial structure that was unoccupied at the time of the fire. Heavy fire damage was observed throughout the attic and inside the A side main entrance to the structure. Large sections of the roof closer to the A side had collapsed. At this time the fire is being ruled undetermined. An unspecified electrical event in the attic near the A side main entrance could not be ruled out, nor could a portable heater located just inside the A side main entrance. This case remains open pending further investigation.

Subject #1 - VIC1	FIM #1 - SANTORO, MICHAEL J
Primary Informatio	on de la constante de la consta
Subject Name:	SANTORO, MICHAEL J
Record Type:	PERSON
Bio:	(c)
Birth Date:	(c)
Juvenile:	(c)
Relationship Inform	nation
Victim Type:	(c)
Extent Of Injury:	(c)
Personal Informati	ion
Height: (c)	
Addresses	
<u>Relationship</u>	Address
MAILING ADDRES	SS (c)
Telephones / E-Ad	dresses
Relationship USER - COMMER RECORD SOURCE	



Massachusetts State Police

FIRE INVESTIGATION REPORT 2022-117-170

Report Date: 03/03/2022

Subject #2 - OW	NER #1 - HAJJAR, CHARLES CHRISTOPHER
Primary Information	on
Subject Name:	HAJJAR, CHARLES CHRISTOPHER
Record Type:	PERSON
Bio:	(c)
Birth Date:	(c)
Juvenile:	(C)
Relationship Infor	rmation
Extent Of Injury:	(c)
Personal Informat	tion
Height: (c)	
Addresses	
Relationship	Address
MAILING ADDRE	SS (c)
	NER #2 - SANTORO, MICHAEL J
Primary Information	on
Subject Name:	SANTORO, MICHAEL J
Record Type:	PERSON
Bio:	(c) Unknown, MALE
Birth Date:	(c)
Juvenile:	
Relationship Infor	rmation

Extent Of Injury: (c)	
Personal Information	
Height: (c)	
Addresses	
<u>Relationship</u>	Address
MAILING ADDRESS	(c)
Telephones / E-Addresses	
Relationship	Number/E-Address
USER - COMMERCIAL RECORD SOURCED	(c)

Officers

<u>LEO</u> Colella, James M. (msp3557 / Fire Investigation Southeast Team / Massachusetts State Police) Shaw, Dustin (Massachusetts State Police Cape and Islands SPDU) Garfield, Beth E (msp3798 / Crime Scene Services Bourne / Massachusetts State Police) Mackin, David (msp2548 / D5 State Police Oak Bluffs / Massachusetts State Police)



Massachusetts State Police
FIRE INVESTIGATION REPORT 2022-117-170

Report Date: 03/03/2022

Narrative begins on the following page.

Introduction:

- On Thursday, March 3, 2022 at approximately 0952, the Oak Bluffs Fire Department responded to 16 Chapman Ave for a report of a structure fire. Fire and smoke alarms were present inside the building which alerted the Central Station Alarm Company, who then notified Dukes County Communication Center. Emergency personal were then dispatched to the scene. The weather at the time of the alarm was partly cloudy skies and the temperature was approximately 40 degrees. The site of the alarm was a 1.5 story wood frame structure. The structure is a restaurant that was temporarily closed for minor renovations. The structure was unoccupied at the time of the fire.
- 2. A working fire was ordered by the fire department. Suppression operations were immediately begun. The fire was not quickly extinguished and quickly went to 3 alarms. Initially, Oak Bluffs Fire Captain John O'Donnell was the incident commander and Deputy Fire Chief Stephen Foster took over command operations around noon time. There were no deaths and no injuries as a result of the fire. The fire did not extend to any adjoining properties. The fire caused extensive damage to the entire structure.
- 3. On Thursday, March 3, 2022, the State Police Fire and Explosion Investigation Unit was notified of this fire by the DHQ duty office. I, Tpr. Myers (FEIU) responded to the incident along with Sgt. Berteletti (FEIU), and Tpr. Colella and AK9 Folton (FEIU). I was assisted by Tpr. Garfield (CSSS) who photographed the scene. At the scene, we met with Sgt. Mackin (D5), Tpr. Shaw (Cape and Islands SPDU), and Deputy Chief Foster and a joint investigation was conducted. As a result of this investigation, the fire has been ruled undetermined.

Building Information:

1. The site of the fire was a 1.5 story wood frame with wood shingle siding and asphalt roof shingles. The structure was used as a restaurant and has approximately 15,000 square feet of space. The structure faces east onto Chapman Ave.



Witness Statements:

- The investigation conducted several interviews with witnesses. The first one on scene was Oak Bluffs Police Officer Christopher Wiggin. Officer Wiggin was interviewed on scene. He stated as he arrived on scene, he observed heavy smoke puffing out of the A side middle of the structure. He didn't observe any vehicles in the parking lot and did not see any doors that appeared to be open.
- 2. The first fire personnel on scene was Captain Medeiros and Medic Davey. Captain O'Donnell arrived shortly after with the first due engine 523. Captain O'Donnell stated upon doing a 360 of the building, he noticed heavy smoke coming from the A side of the building near the dining room entrance. As fire units went to start venting the building, the fire self-vented through the A side roof near the dining room entrance. According to fire personnel, no doors were unlocked and forced entry was made into all doors of the structure.



Fire Scene Examination:

 On March 3, 2022 at approximately 1530, an examination of the fire scene was conducted by Sgt. Bertiletti, Tpr. Colella, and I, Tpr. Myers. Special assistance was provided by Sgt. Mackin (D6), Tpr. Shaw (Cape and Islands SPDU), and Tpr. Garfield (CSSS) who photographed the scene. Entry into the premises was made immediately after fire suppression.

- 2. Exterior examination of the fire site revealed the roof in the middle of the building, closest to the A side had completely burned away/collapsed. Interior examination was conducted beginning in areas of least damage, toward areas of heaviest damage. This process revealed that the lowest and most substantial area of fire damage was located just inside the main entrance of the structure, which was the lobby and hostess desk area for the restaurant. With the exception of this area, the major damage had been contained to the attic and roof of the structure. The joists above the lobby area sustained heavy damage and some of them were completely burned away.
- 3. The investigation revealed the low burn area was the main lobby and hostess desk area for the restaurant. The hostess desk was in the A/B corner of the lobby. There were numerous electrical appliances in the area including a register and a portable heater. These could not be ruled out as potential ignition sources. There were also numerous electrical switches witch contained about 12-14 light dimmers, according to the owner, Mike Santoro. These could also not be ruled out as potential ignition sources. On the C side of the lobby was a large fish tank which according the owner had been shut off and there were no fish or water inside the tank. Underneath the fish tank was a small cabinet with PVC piping and an electrical power strip. There was very little damage inside this cabinet. The power strip was intact with very little damage and was subsequently ruled out as an ignition source. Numerous BX cables were found hanging from the ceiling in the area of origin. The wires had varying degrees of damage to them and could not be ruled out as ignition sources.
- 4. Tpr. Colella deployed AK9 Folton in the area of origin with negative results. See Tpr. Colella's AK9 report.

Security and Fire Protection:

1. According to interviews with the first fire and police assets on scene, none of the doors to the structure were open and the fire department had to force entry into all of the doors. All of the windows also appeared to be intact upon arrival of the first assets. The structure was outfitted with a fire alarm system. The system appeared to work as it was supposed to. During the fire, the system detected smoke and an alarm went through to the Central Station Alarm Company. The Central Station Alarm Company then notified Dukes County Communication Center.

Conclusions:

- 1. Based upon the information developed through the investigation, it is this the collective opinion of the investigators that the area of origin was in the ceiling of the lobby/ hostess area, inside the main entrance to the building on the A side. Further, it is the collective opinion of the investigators that this fire was accidental in nature, with the most likely cause being and unspecified electrical event. There is no evidence of criminal activity at this time. This case will remain undetermined.
- 2. I respectfully request that this case be closed pending any further discoveries that should warrant its reopening.



Massachusetts State Police

ACCELERANT DETECTION K-9 REPORT 2022-117-170/1

Report Date: 03/04/2022

Primary Information	
Description:	16 Chapman Ave, oaks Bluffs
Dissemination Code:	report respect the security of its associated case
Reporting LEO:	Colella, James M. (msp3557 / Fire Investigation Southeast Team / Massachusetts State Police)
Report Status:	Approved
Report Status Date:	03/17/2022
Approved By:	Berteletti, Thomas (msp2708 / Massachusetts State Police)

Synopsis

On Thursday, March 3, 2021, I responded to 16 Chapman Ave in Oak Bluffs (MV) to assist Sgt. Berteletti and Tpr. Myers with an ongoing fire investigation to the Ocean View Restaurant & Tavern. During the course of the investigation AK-9 Fulton was deployed into the scene to search for the presence of ignitable liquids. This search provided negative results.