

# 4 State Road - Cherry Tree

Xerxes Agassi <xerxes@delanoandco.com>


Tue 5/10/2022 12:51 PM

To: Alex Elvin <elvin@mvcommission.org>;

Cherry Tree -

See below - we have over 10ft+ circumference around the trunk before the sunken patio - Closer to 14' going west - I spoke to Donoroma's who suggested I reach out to Bob Haggerty at Hagerty Tree Services and Ian Jochems at Poly Hill Arboretum. I spoke to both who advised that they offer consulting services and given the space they felt that there was enough room to save the tree and that treatments would help. We would leverage the services of an arborist as we would like the tree and intend on keeping it. The MVC can condition us to hire an arborist to consult with and/or replace with a tree in kind if it doesn't survive as they see fit. Our goal is to keep it.





SB F

⊕ 20.0

EXIT  
ONLY

20/



⊕ 20.0

14'-0"

2.0'

LAND  
SCAPING

14'-0"

⊕ 14.6

⊕ 14.5